ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0885	NA	2nd Cross Chikkavenkatappa Layout
Segment No.	**Total Length (m)**	
9/S-W0885/S022533	81.83	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	81.83	77.564979	13.059799	77.564476	13.059248	1st Main	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Deshabanndunagara and Surrounding areas in Ward No. 09 (Vidyaranyapura).	4700000	2021-22
Year	**Type of Work**	**Other Work Type**
2021 - 2022	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Constrction of RCC Drain and Providing Covering Slab	009-22-000010
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/54/2022-23	29/06/2022	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/07/2022	29/07/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Nagoor Lokanadha Reddy		0.00
Phone No.	**E-Mail ID**	
9844313439		

CHIKKAVENKATAPPA LAYOUT COMES UNDER THIS AREA
THIS ROADS COMES UNDER DESHABANDUNAGARA.

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Somnath s jadhav

Date of Inspection	Remarks
30/09/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	30/09/2022	30/10/2022	As proposed
SE	Swayam Prabha	30/09/2022	30/10/2022	Forwarded
EE	Pradeep B N	30/09/2022	30/10/2022	Forwarded as recomended by AE and AEE
AEE	Beeresh V N	30/09/2022	30/10/2022	Verified
AE	Somnatha S Jadhav	30/09/2022	30/10/2022	Mobile Verification Done
AE	Somnatha S Jadhav	30/09/2022	30/10/2022	Forward

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0883	NA	1st Cross Road Chikkavenkatappa Layout
Segment No.	**Total Length (m)**	
9/S-W0883/S022343	98.55	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	98.55	77.564252	13.059414	77.564836	13.060097	1st Main	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Deshabanndunagara and Surrounding areas in Ward No. 09 (Vidyaranyapura).	4700000	2021-22
Year	**Type of Work**	**Other Work Type**
2021 - 2022	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of RCC Drain and Providing Covering Slabs	009-22-000010
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/54/2022-23	29/06/2022	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/07/2022	29/07/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Nagoor Lokanadha Reddy		0.00
Phone No.	**E-Mail ID**	
9844313439		

CHIKKAVENKATAPPA LAYOUT COMES UNDER THIS AREA
THIS COMES UNDER DESHABANDUNAGAR.

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Somnath s jadhav

Date of Inspection	Remarks
30/09/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	30/09/2022	30/10/2022	As proposed
SE	Swayam Prabha	30/09/2022	30/10/2022	Forwarded
EE	Pradeep B N	30/09/2022	30/10/2022	Forwarded as recomended by AE and AEE
AEE	Beeresh V N	30/09/2022	30/10/2022	Verified
AE	Somnatha S Jadhav	30/09/2022	30/10/2022	Mobile Verification Done
AE	Somnatha S Jadhav	30/09/2022	30/10/2022	Forward

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0586	NA	Chikkavenkatappa Layout Main Road
Segment No.	**Total Length (m)**	
9/S-W0586/S021253	364.89	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	364.89	77.565581	13.058880	77.563192	13.058871	Main Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Deshabanndunagara and Surrounding areas in Ward No. 09 (Vidyaranyapura).	4700000	2021-22
Year	**Type of Work**	**Other Work Type**
2021 - 2022	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of RCC Drain and Providing Covering Slabs	009-22-000010
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/54/2022-23	29/06/2022	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/07/2022	29/07/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Nagoor Lokanadha Reddy		0.00
Phone No.	**E-Mail ID**	
9844313439		

CHIKKAVENKATAPPA LAYOUT COMES UNDER THIS AREA
THIS ROADS COMES UNDER DESHABANDUNAGAR

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Somnath s jadhav

Date of Inspection	Remarks
30/09/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	30/09/2022	30/10/2022	As proposed
SE	Swayam Prabha	30/09/2022	30/10/2022	Forwarded
EE	Pradeep B N	30/09/2022	30/10/2022	Forwarded as recomended by AE and AEE
AEE	Beeresh V N	30/09/2022	30/10/2022	Verified
AE	Somnath S Jadhav	30/09/2022	30/10/2022	Mobile Verification Done
AE	Somnath S Jadhav	30/09/2022	30/10/2022	Forward

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike